

Wear Resistance TLT Axial Fan Blade 15MnV Steel Industrial Fan Blade Replacement

Basic Information

. Place of Origin: Shanghai YIKU . Brand Name: S1GA6889 Model Number: Minimum Order Quantity: 1 piece • Price: negotiable Packaging Details: Wooden box . Delivery Time: 2-3month • Payment Terms: L/C, T/T • Supply Ability: 20 units/month



Product Specification

Name: Steel Blade S1GA6889 Model: 15MnV Material: 20.9kg · Weight:

• Purpose: Extract Flue Gas For Desulfurization And

Purification

• Applicable To: Induced Draft Fan • Highlight: Axial Fan Blade 15MnV,

15MnV Industrial Fan Blade Replacement,


wear resistance Axial Fan Blade

Our Product Introduction

Product Description

15MnV Steel blade fan impeller blade

配叶片、叶柄孔和叶柄的序号 Assembly blade, handle hole and handle senal No



在 力,,水泥,造 等行 中大量使用的 机 ,因 送的气体介 中含有大量的硬 粉 粒和酸性气体, 些 的 流部件,受到 烈的冲刷腐 ,尤其是 其心 部件叶,在其叶片的末端 行速度 到160米 秒,磨速度比其它部位更 重.尤其是 机叶片的磨 最 重,因而使机 子的平衡遭到破 坏,引起 机振,短 机寿命,重 可使 机不能正常工作. 然使用 各 表面防磨措施如堆,,,覆高分子耐磨材料等,使用寿命也 以得到 著 提高,比 常用的方法中超音速 弧 硬 合金耐磨 用.

Fan equipment widely used in the electric power, steel, cement, paper and other industries, because the gas medium contains a large number of hard dust particles and acidic gases, the flow parts of these equipment are strongly eroded and corroded, especially the heart part of the impeller, the running line speed at the end of the blade reaches 160 meters per second, and the wear rate is more serious than other parts. In particular, the wear of the fan blade is the most serious, so that the balance of the fan rotor is destroyed, causing fan vibration, shortening the life of the fan, and in serious cases, the fan can not work normally. Although the use of a variety of surface anti-wear measures such as surfacing, spraying, spray welding, coating polymer wear-resistant materials, etc., the service life is difficult to be significantly improved, the more commonly used methods of supersonic arc thermal spraying carbide wear-resistant coating economic and practical.

上海依库机电设备 Shanghai YIKU Power Equipment Co., Ltd



8613916002258



657925203@qq.com



axialfanparts.com

5587 Dongchuan Road, Pudong New Area, Shanghai